

General Environmental Incident Summary

Incident: 3288 **Date/Time Notice:** 4/15/2014 **DEM Incident No:**

Responsible Party: Sanjel

Date Incident: 4/12/2014 **Time Incident:** **Duration:**

County: Williams **Twp:** 154 **Rng:** 99 **Sec:** 1 **Qtr:**

Lat: 48.19651 **Long:** -103.34880 **Method:** Interpolation from map

Location Description: P Vandenberg 154-99-1-1-12-154H

Submitted By: Alan Heltemes

Affiliation:

Address: 511 22nd Ave NE

City: Williston

State: ND

Zip:

Received By:

Contact Person:

511 22nd Ave N.E
Williston, ND 58801

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Discharge hose failure

Description of Released Contaminant: Crosslinked Fracturing fluid

Volume Spilled: 10.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Hose failure

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Spilled product was immediately cleaned up by a vac truck and handled in accordance with state and federal law

Wastes Disposal Location: All spilled product was disposed of in accordance with customer direction

Agencies Involved:

Updates

Date: 4/15/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release of fracking fluid from a broken hose remained on location according to the report. Release occurred on an E&P location. Report forwarded to NDIC for oversight.